

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,967,424 B2  
APPLICATION NO. : 10/758109  
DATED : November 22, 2005  
INVENTOR(S) : Vladimir Vladimirovich Popov

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the drawings:

in Figure 1 show the angles indicated as 2.5, 7.5 and 12.5 degrees measured between the center line of the slots 12 and the center line of the shallow notches 20. A corrected Figure 1 is shown on attachment page 2 of 3;

in Figure 2a show groove 200 to be in the same tangential position with regard to the slots of laminations 10-1, 10-2, 10-3, 10-4, 10-5 and 10-6. A corrected Figure 2a is shown on attachment page 3 of 3; and

in Figure 2b show groove 201 to be in the same tangential position with regard to the slots of laminations 10-1, 10-2, 10-3, 10-4, 10-5 and 10-6. A corrected Figure 2b is shown on attachment page 3 of 3.

Signed and Sealed this

Third Day of October, 2006




JON W. DUDAS  
*Director of the United States Patent and Trademark Office*

U.S. Patent

Nov. 22, 2005

Sheet 1 of 5

6,967,424 B2



U.S. Patent

Nov. 22, 2005

Sheet 2 of 5

**6,967,424 B2**

Fig. 2a




Fig. 2b

